




Поз	Наименование детали				
1	top cover	37	flat washer	73	Hexagon socket set screw with flat point
2	control board	38	gasket washer	74	long pin
3	timer	39	hexagon bolt	75	protective cover limit block
4	start button	40	flat key	76	travel switch press wheel
5	stop button	41	up&down drive shaft	77	protective cover
6	frame	42	flat key	78	bowl
7	foot	43	adjusting screw	79	lower shaft welding parts
8	hexagon nut	44	bearing	80	flat washer
9	spring washer	45	hexagon nut	81	spring washer
10	flat washer	46	spring washer	82	hex nut
11	travel switch seat	47	flat washer	83	flat key
12	cross recess pan head screw	48	gasket washer	84	bearing
13	travel switch	49	hexagon bolt	85	bearing
14	v-belt	50	belt wheel-3	86	circlip for shaft
15	small triangle belt pulley	51	flat washer	87	criclip for hole
16	flat key	52	spring washer	88	belt wheel-4
17	motor	53	hexagon thin nut	89	flat washer
18	hexagon bolt	54	v-belt	90	spring washer
19	spring washer	55	back cover	91	hexagon thin nut
20	gasket washer	56	cross recess pan head screw		
21	auxiliary contact	57	flat washer		
22	auxiliary contact	58	spring washer		
23	a.c capacitor	59	hexagon socket cap screws		
24	a.c capacitor	60	fix rod		
25	line contact bank	61	right-handed nut		
26	electrical plate	62	Blade washer		
27	v-belt	63	belt wheel-1		
28	hexagon thin nut	64	large triangle belt pulley		
29	spring washer	65	circlip for hole		
30	flat washer	66	circlip for shaft		
31	belt wheel-2	67	bearing		
32	shaft sleeve	68	bearing		
33	adjusting screw	69	flat key		
34	bearing	70	upper shaft welding parts		
35	hexagon nut	71	sprial		
36	spring washer	72	hexagon socket cap screws		