




Поз	Наименование детали
1	Rubber feet
2	Screw M3X12
3	Bottom under base
4	Power cord
5	Capacitor
6	Over Current protector
7	Scvrew M4X14
8	Motor
9	Screw M4X8
10	Housing
11	Switch
12	Bottom upper base
13	Fixed plate
14	Screw M4X12
15	Tray
16	Oil seal
17	Rotation shaft
18	Damping ring
19	Bowl
20	Pip filter
21	Cone L
21	Cone M
21	Cone S