

Рис.1




Рис.2





Рис.3



Модель	Рис.	L, мм	a, мм
3BH-С(Б,Л)-1-500.800.500-02	1	500	-
3BH-С(Б,Л)-1-800.800.500-02	2	800	-
3BH-С(Б,Л)-1-1000.800.500-02		1000	-
3BH-С(Б,Л)-1-1200.800.500-02		1200	-
3BH-С(Б,Л)-1-1400.800.500-02		1400	-
3BH-С(Б,Л)-1-1600.800.500-02		1600	-
3BH-С(Б,Л)-1-1800.800.500-02	3	1800	900
3BH-С(Б,Л)-1-2000.800.500-02		2000	1000