




Поз	Наименование детали
1	Rubber Feet
2	Bottom Plate
3	Power Cord
4	Power Switch
5	Overload Protection Switch
6	Bottom Frame
7	Cover for Motor
8	Motor
9	Capacitor
10	Hook
11	Square positioning pin
12	Middle Frame
13	Round Pad
14	Filte
15	Cover for Motor
16	Blade
17	Hexagon fixing bolt
18	Dreg Pipe
19	Lock
20	Top Cover
21	Pusher